


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 17882	Main Street: CHELSEA_DR	Cross Street: WALES_AV	Location: SE
ADA ID: E0CC8B02CBB5	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No
		Severity Score: 25	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	112.0	Yes	Ramp Slope (%)	7.5
			Yes	Ramp Width (in)	52.0	Yes	Ramp XSlope (%)	1.5
			N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	7.7	Yes	Flare Slope RT (%)	3.7
			N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
			Yes	Landing Length (in)	51.5	No	DWS Provided?	No
			Yes	Landing Width (in)	54.0	N/A	DWS Contrast?	No
			Yes	Landing Slope (%)	1.2	N/A	DWS Length (in)	N/A
			Yes	Landing X Slope (%)	0.4	N/A	DWS Full Width?	No
<p>Surveyor Notes:</p> <p>N/A</p> <p>PROW/ADA:</p> <p>Not Found, R305, R302.7, R302.7.2</p>			N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	Yes			
			No	Gutter Ponding?	Yes	Yes	Gutter Slope (%)	5.0
			No	Gutter Lip Ht (in)	1.5	Yes	Gutter X Slope (%)	0.6
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To W		X Walk 2 Direction	N/A
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	N/A
				X Walk 1 X Slope (%)	0.9		X Walk 2 X Slope (%)	N/A
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
			Road Slope (%)	N/A	N/A	Clear Space?	Yes	
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
		Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
			Obstruction Type			Storm Grate/Utility Type		
					N/A			N/A
						Yes	Surface Condition? (G/P)	Good

