

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 54269	Main Street: JOHNSTON_OEHLER_RD	Cross Street: OEHLER_BRIDGE_DR	Location:	N
ADA ID: E104A9D36363	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 5

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Landing.		N/A	Ramp Length (in)	96.0	Yes	Ramp Slope (%)	7.7
	Remove & Replace Gutter.		Yes	Ramp Width (in)	70.0	Yes	Ramp XSlope (%)	0.8
			Yes	Flare Type LT	Curbed_NoWalkSurface	Yes	Flare Type RT	N/A
			Yes	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
			Yes	Landing Length (in)	71.0	Yes	DWS Provided?	Yes
			Yes	Landing Width (in)	85.5	Yes	DWS Contrast?	Yes
			No	Landing Slope (%)	2.4	Yes	DWS Length (in)	24.0
			Yes	Landing X Slope (%)	0.6	Yes	DWS Full Width?	Yes
Surveyor Notes:		No	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	0.0	
N/A		N/A	Shared Landing?	No				
PROW/ADA:		Yes	Gutter Ponding?	No	No	Gutter Slope (%)	7.4	
R304.2.2-Perp, R304.3.2-Para, R304.5.4		Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.4	
		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
			X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
		N/A	X Walk 1 Width (in)	112.0	N/A	X Walk 2 Width (in)	N/A	
			X Walk 1 Slope (%)	2.1		X Walk 2 Slope (%)	N/A	
			X Walk 1 X Slope (%)	2.6		X Walk 2 X Slope (%)	N/A	
		Yes	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
			Road Slope (%)	N/A	N/A	Clear Space?	Yes	
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
		Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
			Obstruction Type			Storm Grate/Utility Type		
					N/A		N/A	
					Yes	Surface Condition? (G/P)	Good	
Total Cost:		\$ 1250.00						

