## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 25769 Main Street: PINEVILLE-MATTHEWS_RD Cross Street: CARMEL_COMMONS_BV								Location:	SE	
ADA ID: E13011DE11				nitial Pass/Fail: Fail Overall Compliance: No					12.5	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:					ta Compliance Description		Data	
- L		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	ith M	I/A	Ramp Length (in)	75.0	No	Ramp Slope (%)	11.1	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				′es I/A	Ramp Width (in) Flare Type LT	48.0 N/A	Yes N/A	Ramp XSlope (%) Flare Type RT	1.1 N/A	
			١	I/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
C DNEVILLE	MATTHEWS RD			I/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
FILLISCO	- C-			I/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		I/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
A A A A A A A A A A A A A A A A A A A	G. C.	N/A		I/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
PROW/ADA: Not Found, R304.2.2				I/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
				I/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				I/A	Shared Landing?	N/A				
				I/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
				/ <b>A</b>	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
			1	I/A	Painted X Walk1?	No	N/A	Painted X Walk2?	Yes	
	1 DESCHI VALS				X Walk 1 Direction	To N		X Walk 2 Direction	To W	
			1	I/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	125.0	
Street 1 Name	PINEVILLE-MATTHEWS RD				X Walk 1 Slope (%)	0.8		X Walk 2 Slope (%)	0.6	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.0		X Walk 2 X Slope (%)	0.5	
Street 2 Name	CARMEL COMMONS BV		1	I/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	Yes	
Stop Condition-Street 1	StopSign				Road Slope (%)	0.7	N/A	Clear Space?	N/A	
					Road X Slope (%)	1.6	N/A	Clear Space to XWalk (in)	N/A	
			1	I/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$ 32	00.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	
							Yes	Surface Condition? (G/P)	Good	

