

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 45130	D: 45130 Main Street: DULIN_CREEK_BV				Cross Street: PLAZA_RD_EXT				Location:	NE	
ADA ID: E1A55E9591A6	Ramp Ty	Ramp Type: Combination2			Initial Pass/Fail: Fail Overall Complian			ce: N	o Severity Score:	33.75	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:			Compliance Description			Data Compliance Description			
		Remove & Replace	e Entire Ram).	N/A	Ramp Length LT (in)	62.5	N/A	Ramp Length RT (in)	62.5	
	14 514 B		-		No	Ramp Width LT (in)	36.5	N/A	Ramp Width RT (in)	36.0	
A A A A A A A A A A A A A A A A A A A					No	Ramp Slope LT (%)	10.1	N/A	Ramp Slope RT (%)	0.6	
					No	Ramp XSlope LT (%)	2.6	N/A	Ramp XSlope RT (%)	2.1	
A A A A A A A A A A A A A A A A A A A	A NASA TH				N/A	Ramp Length (in)	24.0	Yes	Ramp Slope (%)	6.0	
					Yes	Ramp Width (in)	72.0	No	Ramp XSlope (%)	5.3	
	11. 1. 16 CO	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	22. 146-	RT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
PLAZA RD BU					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
E.	(Rindle				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	The states				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
the second se	and the	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
		Not Found, R304.5.1, R304.5.3, R304.3.2			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
	and the second s				N/A	Shared Landing?	N/A				
				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
Street 1 Name	StopSign				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	DULIN CREEK BV				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To W		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	83.0		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	1.2		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$	1600.00	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				Here and the second	State Fi			N/A	Any Obstruction?	N/A	
	Summerers				1				Obstruction Type		
	-)		A A		a tradition					N/A	
		port - Trees	A Contraction of the second se					N/A	Storm Grate/Utility Hazard?	N/A	
			-		1-	Stars and a star and a star			Storm Grate/Utility Type		

 Storm Grate/Utility Type

 N/A

 Yes
 Surface Condition? (G/P)

 Curb Slope (%)
 14.0