cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 32285	Main Street: ALLYSON_PARK_DR			Cross Street: AUBURN_TOP_LN				Location:	NE
ADA ID: E1B71A97218D	Ramp Type: PerpDiag			nitial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		Data Compliance Description		Data	
-		Remove & Replace Curb Rar	np With	N/A	Ramp Length (in)	47.0	Yes	Ramp Slope (%)	7.5
		Two New Directional Ramps	•	Yes	Ramp Width (in)	50.0	No	Ramp XSlope (%)	5.7
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
E ALTER				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Club b			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
6.			N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		3			X Walk 1 Direction	To W		X Walk 2 Direction	To S
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name AUBL	JRN TOP LN	-			X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	0.8
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	0.0
Street 2 Name ALLYSO	ON PARK DR			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign				Road Slope (%)	0.6	N/A	Clear Space?	N/A
					Road X Slope (%)	1.1	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

