

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 44421 Main Street: CENTRAL_AV Cross Street: ALBEMARLE_RD Location: NW

Overall Compliance: No ADA ID: E1F6D2A3B426 Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 33.75

Codes/Mitigation Info/Possible Solution



ALBEMARLE RD Street 1 Name Signal Stop Condition-Street 2 Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:	<u>c</u>
Remove & Replace Entire Ramp.	N
	N
	N
	N
	N
	N
Surveyor Notes:	N
N/A	N
	N
	N
	N
PROW/ADA:	N
Not Found, R304.5.1, R304.5.3	N
	N
	N
	N

Total Cost: 1850.00

Field Measurements/Component Compliance							
Compliance Description		Data	Comp	liance Description	Data		
N/A	Ramp Length (in)	60.5	Yes	Ramp Slope (%)	5.1		
No	Ramp Width (in)	42.5	No	Ramp XSlope (%)	9.5		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To SE		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	110.0	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	1.9		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	4.9		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		
	200						





