cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interestion ID: N/A	Mela Ot		0	tus st-				Lesstien	05	
Intersection ID: N/A	Main Street: MARSHALL_BRIDGE_RD			Cross Street: WALNUT_LOOP_RD				Location:	SE	
ADA ID: E1F714E07AE	EA Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	C Y	Possible Solutions:		Compliance Description			Data Compliance Description			
a thing the first		Remove & Replace Entire Ramp	-	N/A	Ramp Length (in)	71.0	No	Ramp Slope (%)	8.7	
				Yes	Ramp Width (in)	96.0	Yes	Ramp XSlope (%)	0.8	
	Contraction of the			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	11-dans	8		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	Card Bake			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
100 MALLE CONTRACT	Bar and Second			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
CONTRACTOR AND	April 1 - Anna	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
E. Co		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	S SALLY			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	THE AND THE			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	i la contra com	Not Found, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
	States Land				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A	
· · · · · · · · · · · · · · · · · · ·	and the second second			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	MARSHALL BRIDGE RD				X Walk 1 Slope (%)	0.3		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	2.5		X Walk 2 X Slope (%)	N/A	
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	
4							1			

s Surface Condition? (G/P)

Good

