cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 1003	Main Str	eet: PINEVILLE-MATTHEWS_RD	Cross Str	eet:	N/A			Location:	NW
ADA ID: E21AA0AED	E21AA0AED31F Ramp Type: PerpDiag			s/Fa	il: Fail Overall C	o Severity Score:	21.25		
Codes/Mitigation Info/Possible Solution Field Measurements/Component Co								nent Compliance	
		Possible Solutions:	C	ompl	ance Description Data		Compliance Description		Data
ŝ		Remove & Replace Curb Ramp W	/ith N	/ A	Ramp Length (in)	59.0	No	Ramp Slope (%)	9.3
Tota or and the		Two New Directional Ramps or	N	0	Ramp Width (in)	46.5	Yes	Ramp XSlope (%)	1.5
		Equivalent.	N	/ A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
Barristin			N	/ A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
Enn St. Eng			N	/ A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
All stands	X X X MILL		Ν	/ A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
A DECEMBER OF THE OWNER OWNE	XXX	Surveyor Notes:	N	/ A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
100	L. B	N/A	N	/ A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	MATTHEWS RD		Ν	/ A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A STATE OF	HULLING RD		N	/ A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	and the second second		N	/ A	Shared Landing?	N/A			
	A CONTRACT	PROW/ADA:	N	/ A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	A B B P AC B	Not Found, R304.5.1, R304.2.2	N	/ A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Start 1			Ν	/ A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
Park 1	and the second s				X Walk 1 Direction	To W		X Walk 2 Direction	To S
A MAR			Ν	/ A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE				X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	1.1
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.0		X Walk 2 X Slope (%)	1.6
Street 2 Name	PINEVILLE MATTHEWS RD		Ν	/ A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	0.8	N/A	Clear Space?	N/A
					Road X Slope (%)	0.7	N/A	Clear Space to XWalk (in)	N/A
			N	/ A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
							Yes	Surface Condition? (G/P)	Good

