


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 51776	Main Street: MCVAY_ST	Cross Street: ORANGE_ST	Location: SE
ADA ID: E2B41B4822BC	Ramp Type: Directional1	Initial Pass/Fail: Fail	Overall Compliance: No
Severity Score: 1.25			
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance	

	Possible Solutions:						
	Remove & Replace Entire Ramp.						
	Surveyor Notes: N/A	Compliance	Description	Data	Compliance	Description	Data
		N/A	Ramp Length (in)	74.0	N/A	Grade Break?	N/A
		Yes	Ramp Width (in)	60.0	N/A	Grade Break Slope (%)	0.0
		Yes	Ramp Slope (%)	5.5	N/A	Grade Break XSlope (%)	0.0
		No	Ramp XSlope (%)	3.0			
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
PROW/ADA: R304.5.3	N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
	N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
	N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
	N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
	N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
	N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
	N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
	N/A	Painted X Walk1?	No		Road Slope (%)	4.6	
		X Walk 1 Direction	To N		Road X Slope (%)	2.6	
		X Walk 1 Width (in)	N/A		Clear Space?	N/A	
		X Walk 1 Slope (%)	4.6	N/A	Clear Space to XWalk (in)	N/A	
		X Walk 1 X Slope (%)	2.6	N/A	Storm Grate/Utility Hazard?	N/A	
	N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
	N/A	Any Obstructions?	N/A			N/A	
	Obstruction Type		Yes	Surface Condition? (G/P)	Good		
		N/A	N/A	Curb Slope (%)	13.5		
Total Cost:	\$	1600.00					

