

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15897	Main Str	Main Street: LOCKHART_DR			CLAYTON_DR	Location:	NE		
ADA ID: E2BEA8AC0347	Ramp Ty	Initial Pas	Initial Pass/Fail: Fail Overall Compliance: N				o Severity Score:	1.25	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	A how	Possible Solutions:	Compliance Description			Data Compliance Description		Data	
A The second of	6	Remove & Replace Entire Ramp	. 1	N/A	Ramp Length (in)	80.0	N/A	Grade Break?	N/A
(2)	A A			<b>í</b> es	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0
A Contraction of the second se	1 AN 12		١	/es	Ramp Slope (%)	5.8	N/A	Grade Break XSlope (%)	0.0
			Ν	No	Ramp XSlope (%)	4.7			
Start Start	L'L K		Ν	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
A STA	1 million		Ν	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
6.		Surveyor Notes:	Ν	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Que E		N/A	Ν	N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
A B WID	- A.		M	N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
	AND I		M	N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
	1000		Ν	N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	- All	PROW/ADA:	M	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
	What he had	R304.5.3	M	N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	C C K		M	N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
	A PAR		1	N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
			M	N/A	Painted X Walk1?	No		Road Slope (%)	2.8
Street 1 Name	LOCKHART DR				X Walk 1 Direction	To W		Road X Slope (%)	4.3
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	2.8	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	4.3	N/A	Storm Grate/Utility Hazard?	N/A
			Ν	N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
			١	N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	12.6

