

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: TAMARACK DR **Cross Street: SINGLELEAF LN** Location: **Overall Compliance: No** ADA ID: E2F770301BBE Ramp Type: Perp Initial Pass/Fail: Fail Severity Score: 33.75

Codes/Mitigation Info/Possible Solution



SINGLELEAF LN Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions:	9
Remove & Replace Entire Ramp.	N
	N
	N
	N
	N
	N
Surveyor Notes:	N
N/A	N
	N
	N
	N
PROW/ADA:	N
Not Found, R304.5.1, R304.2.2	N
	N
	N
	N





Total Cost:



1850.00

Field Measurements/Component Compliance							
Compl	iance Description	Data	Compl	iance Description	Data		
N/A	Ramp Length (in)	50.0	No	Ramp Slope (%)	12.2		
No	Ramp Width (in)	46.0	Yes	Ramp XSlope (%)	0.2		
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No		
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
N/A	Shared Landing?	N/A					
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
	X Walk 1 Direction	To NW		X Walk 2 Direction	N/A		
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	0.4		X Walk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	No	N/A	Ramp inside XWalk2?	N/A		
	Road Slope (%)	N/A	N/A	Clear Space?	N/A		
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm Grate/Utility Type			
		N/A			N/A		
			Yes	Surface Condition? (G/P)	Good		