cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

									85
Intersection ID: 6799	Main Street: KNEIGHTON_LN			Cross Street: W_SUGAR_CREEK_RD				Location:	SE
ADA ID: E31E029FC549	549 Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	ALE CETTO OL LAT	Possible Solutions:		Compliance Description			Data Compliance Description		
1 1 - Care		Remove & Replace Curb Ramp Wi Two New Directional Ramps or Equivalent.	With	N/A	Ramp Length (in)	65.5	No	Ramp Slope (%)	11.5
				Yes	Ramp Width (in)	53.5	No	Ramp XSlope (%)	4.7
				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
A CALL		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
A A A A A A A A A A A A A A A A A A A				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
And the Part	Cler			N/A	Shared Landing?	N/A			
MAR X. I		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	NO. COM	Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
TELT.	· · · · · · · · ·	,,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
155 2 1					X Walk 1 Direction	To N		X Walk 2 Direction	To W
	Print The State			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	KNEIGHTON LN				X Walk 1 Slope (%)	3.8		X Walk 2 Slope (%)	3.8
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	5.1		X Walk 2 X Slope (%)	5.1
Street 2 Name	W SUGAR CREEK RD			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	5.1	N/A	Clear Space?	N/A
					Road X Slope (%)	3.8	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A