

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

| | | | |
|------------------------|--------------------------|-----------------------------|------------------------|
| Intersection ID: 14974 | Main Street: CRESCENT_AV | Cross Street: WILLOUGHBY_ST | Location: SW |
| ADA ID: E326C08858E3 | Ramp Type: Perp | Initial Pass/Fail: Pass | Overall Compliance: No |
| | | | Severity Score: 2.5 |

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Possible Solutions:

**Remove & Replace Entire Ramp.
Gutter Ponding Observed.**

Surveyor Notes:

N/A

PROW/ADA:

**R304.2.2-Perp, R304.3.2-Para,
R305.1.4, R302.7**

| Compliance | Description | Data | Compliance | Description | Data |
|------------|-----------------------|-------|------------|-----------------------------|------|
| N/A | Ramp Length (in) | 112.0 | Yes | Ramp Slope (%) | 5.9 |
| Yes | Ramp Width (in) | 48.0 | Yes | Ramp XSlope (%) | 0.9 |
| N/A | Flare Type LT | None | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| Yes | Landing Length (in) | 61.0 | Yes | DWS Provided? | Yes |
| Yes | Landing Width (in) | 60.0 | Yes | DWS Contrast? | Yes |
| No | Landing Slope (%) | 3.6 | Yes | DWS Length (in) | 24.0 |
| Yes | Landing X Slope (%) | 1.5 | No | DWS Full Width? | No |
| N/A | Landing Curb? (Y/N) | No | Yes | DWS Offset (in) | 0.0 |
| N/A | Shared Landing? | No | | | |
| No | Gutter Ponding? | Yes | Yes | Gutter Slope (%) | 3.6 |
| Yes | Gutter Lip Ht (in) | 0.0 | Yes | Gutter X Slope (%) | 1.7 |
| N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A |
| | X Walk 1 Direction | To SW | | X Walk 2 Direction | N/A |
| N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 3.6 | | X Walk 2 Slope (%) | N/A |
| | X Walk 1 X Slope (%) | 0.6 | | X Walk 2 X Slope (%) | N/A |
| N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | N/A | N/A | Clear Space? | Yes |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| Yes | Any Obstructions? | No | Yes | Storm Grate/Utility Hazard? | No |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | N/A | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |

Total Cost: \$ 2350.00

Street 1 Name **WILLOUGHBY ST**
 Stop Condition-Street 2 **StopSign**
 Street 2 Name **N/A**
 Stop Condition-Street 1 **N/A**

