

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 22092 Main Street: SHARON VIEW RD Cross Street: ROCK CREEK DR Location: W Ramp Type: BlendTrans1 Initial Pass/Fail: Pass **Overall Compliance: No Severity Score:** 5.25 ADA ID: E36D48FDE0B3

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2

ROCK CREEK DR StopSign **SHARON VIEW RD** None

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.3, R304.5.4

Total Cost: 3950.00

Compliance Description		Data	Comp	liance Description	Data
N/A	Ramp Length (in)	122.0	Yes	BlendTrans Slope (%)	1.9
Yes	Ramp Width (in)	61.0	No	BlendTrans XSlope (%)	3.0
N/A	Flare Type LT	Sloped	N/A	Flare Type RT	Sloped
N/A	Flare Slope LT (%)	2.9	N/A	Flare Slope RT (%)	5.2
N/A	Flare Traversable LT?	No	N/A	Flare Traversable RT?	No
Yes	Landing Length (in)	48.0	Yes	DWS Provided?	Yes
Yes	Landing Width (in)	57.0	Yes	DWS Contrast?	Yes
Yes	Landing Slope (%)	0.6	Yes	DWS Length (in)	24.0
Yes	Landing X Slope (%)	1.8	Yes	DWS Full Width?	Yes
N/A	Landing Curb? (Y/N)	No	Yes	DWS Offset (in)	0.0
N/A	Shared Landing?	No			
Yes	Gutter Ponding?	No	No	Gutter Slope (%)	6.8
Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	0.9
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To SE		X Walk 2 Direction	To NE
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.5		X Walk 2 Slope (%)	0.4
	X Walk 1 X Slope (%)	1.1		X Walk 2 X Slope (%)	1.7
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	0.6		Clear Space?	Yes
	Road X Slope (%)	1.2	N/A	Clear Space to XWalk (in)	N/A
Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			No	Curb Slope (%)	17.1





