

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 26025	Main Street: CARMEL COMMONS BV	Cross Street: CARMEL RD	Location: SW
ADA ID: E3795D542657	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance			
	Possible Solutions:		Compliance	Description	Data	Compliance
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A	Ramp Length (in)	117.0	No
			Yes	Ramp Width (in)	48.0	No
			N/A	Flare Type LT	N/A	N/A
			N/A	Flare Slope LT (%)	N/A	N/A
			N/A	Flare Traversable LT?	N/A	N/A
			N/A	Landing Length (in)	N/A	N/A
			N/A	Landing Width (in)	N/A	N/A
			N/A	Landing Slope (%)	N/A	N/A
			N/A	Landing X Slope (%)	N/A	N/A
Surveyor Notes: N/A PROW/ADA: R304.2.2, R304.5.3			N/A	Flare Type RT	N/A	N/A
			N/A	Flare Slope RT (%)	N/A	N/A
			N/A	Flare Traversable RT?	N/A	N/A
			N/A	DWS Provided?	N/A	N/A
			N/A	DWS Contrast?	N/A	N/A
			N/A	DWS Length (in)	N/A	N/A
			N/A	DWS Full Width?	N/A	N/A
			N/A	DWS Offset (in)	N/A	N/A
			N/A	Gutter Ponding?	N/A	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A
Total Cost: \$ 3200.00			N/A	Painted X Walk1?	No	N/A
			N/A	X Walk 1 Direction	To E	N/A
			N/A	X Walk 1 Width (in)	N/A	N/A
			N/A	X Walk 1 Slope (%)	2.9	N/A
			N/A	X Walk 1 X Slope (%)	2.5	N/A
			N/A	Ramp inside XWalk1?	N/A	N/A
			N/A	Road Slope (%)	3.6	N/A
			N/A	Road X Slope (%)	0.5	N/A
			N/A	Any Obstructions?	N/A	N/A
			N/A	Obstruction Type		N/A
			N/A			N/A
			Yes	Surface Condition? (G/P)		Good

