

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 47971 Main Street: SOUTH_CREEK_RD Cross Street: KYRENE_RD Location: N

ADA ID: E3A6D49D991D Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

KYRENE RD StopSign SOUTH CREEK RD None Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1

Total Cost: \$ 3200.00

Compliance Description Data Compliance Description Data Yes Ramp Slope (%) N/A Ramp Length (in) 47.0 5.0 Yes Ramp XSlope (%) No Ramp Width (in) 46.5 0.9 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A N/A DWS Provided? N/A Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To SW X Walk 2 Direction To SE N/A N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) N/A X Walk 1 Slope (%) 0.6 X Walk 2 Slope (%) 2.5 X Walk 1 X Slope (%) 2.6 X Walk 2 X Slope (%) 0.0 N/A N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? Road Slope (%) 2.0 N/A Clear Space? N/A N/A Road X Slope (%) 1.1 Clear Space to XWalk (in) N/A N/A N/A N/A Any Obstructions? Storm Grate/Utility Hazard? N/A

N/A

Yes

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

Good







Obstruction Type