

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 32098 Main Street: DUISKE_ABBY_CT Cross Street: ROTHE_HOUSE_RD Location: NW
ADA ID: E3BADB0F273C Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

ROTHE HOUSE RD None DUISKE ABBY CT StopSign Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Total Cost: \$ 3200.00

Compliance Description Data Compliance Description Data Yes Ramp Slope (%) N/A Ramp Length (in) 51.0 7.3 No Ramp XSlope (%) No Ramp Width (in) 36.0 3.0 N/A Flare Type LT N/A N/A Flare Type RT N/A N/A N/A N/A Flare Slope RT (%) N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A N/A DWS Provided? N/A Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A N/A Landing Slope (%) DWS Length (in) N/A N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A N/A Shared Landing? N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To SE X Walk 2 Direction To NE N/A N/A X Walk 1 Width (in) N/A X Walk 2 Width (in) N/A X Walk 1 Slope (%) 0.7 X Walk 2 Slope (%) 1.7 X Walk 1 X Slope (%) 0.8 X Walk 2 X Slope (%) 1.4 N/A N/A N/A Ramp inside XWalk2? N/A Ramp inside XWalk1? Road Slope (%) 0.2 N/A Clear Space? N/A N/A Road X Slope (%) 3.1 Clear Space to XWalk (in) N/A N/A N/A Any Obstructions? N/A Storm Grate/Utility Hazard? N/A **Obstruction Type** Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good





