

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

41.0

46.5

2.9

1.1

7.1

6.9

N/A

Good

6.2

Intersection ID: 9315 Main Street: DOGWOOD\_AV Cross Street: NORRIS\_AV Location: N

ADA ID: E3C2C85C4462 Ramp Type: Combination2 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 46.25

Compliance Description

Ramp Length LT (in)

Ramp Width LT (in)

Ramp Slope LT (%)

Ramp Length (in)

Ramp Width (in)

Flare Type LT

Ramp XSlope LT (%)

N/A

No

No

No

N/A

No

N/A

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance

N/A

N/A

N/A

N/A

Yes

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Ramp XSlope RT (%)

Surface Condition? (G/P)

Curb Slope (%)

Data

44.0

46.0

13.6

3.2

28.0

47.5 No

N/A N/A



Street 1 Name

Stop Condition-Street 1

NORRIS AV

Street 2 Name

N/A

Stop Condition-Street 2

N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

RT RP < 5%

PROW/ADA:

Not Found, R304.5.1, R304.5.1, R304.5.3, R304.3.2

Total Cost:



1600.00

IN/A	riale Type LT	IN/A	IN/A	Flate Type IXT	IN/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
	X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	6.5		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	2.3		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A		Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstruction?	N/A
N.				Obstruction Type	
					N/A
-			N/A	Storm Grate/Utility Hazard?	N/A
1				Storm Grate/Utility Type	
					N/A

Yes

