

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9521 Main Street: LAKEVIEW_ST					Location:	N			
			Cross Street: NORWOOD_DR						
ADA ID: E3F1579D255C Ramp Type: Perp		Initial F	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	46.25	
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:		Compliance Description Da			a Compliance Description Data			
	Remove & Replace Entire Ram	p .	N/A	Ramp Length (in)	47.0	No	Ramp Slope (%)	12.2	
A STREET AND	- -		No	Ramp Width (in)	42.0	No	Ramp XSlope (%)	5.2	
State The state of the second			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
A THE THE STATE			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
LAKEVIEW - 68	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
the second second			N/A	Shared Landing?	N/A				
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
A STALL STA	Not Found, R304.5.1, R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
MARK THE ALL IN THE	R304.5.3		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
				X Walk 1 Direction	To S		X Walk 2 Direction	N/A	
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name LAKEVIEW ST				X Walk 1 Slope (%)	2.2		X Walk 2 Slope (%)	N/A	
Stop Condition-Street 2 StopSign				X Walk 1 X Slope (%)	5.1		X Walk 2 X Slope (%)	N/A	
Street 2 Name N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1 N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A	
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type		
					N/A			N/A	

Yes Surface Condition? (G/P)

Good





