


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 31810	Main Street: CRANE_POINT_DR	Cross Street: TROTTERS_RIDGE_RD	Location: NE
ADA ID: E40A1EA00EF2	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 12.5	

Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance								
	Possible Solutions:	Compliance		Description		Data	Compliance	Description		Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	N/A	Ramp Length (in)	56.0	No	Ramp Slope (%)	8.4			
		Yes	Ramp Width (in)	48.5	Yes	Ramp XSlope (%)	1.6			
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A			
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A			
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A			
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A			
		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A			
		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A			
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A			
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A					
Surveyor Notes:	Compliance		Description		Data	Compliance	Description		Data	
N/A	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A				
PROW/ADA:	Not Found, R304.2.2	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A			
		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No			
			X Walk 1 Direction	To NW		X Walk 2 Direction	To SW			
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A			
			X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	3.3			
			X Walk 1 X Slope (%)	7.0		X Walk 2 X Slope (%)	0.1			
		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A			
			Road Slope (%)	6.7	N/A	Clear Space?	N/A			
			Road X Slope (%)	10.5	N/A	Clear Space to XWalk (in)	N/A			
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A			
Total Cost:	\$	3200.00	Obstruction Type		Storm Grate/Utility Type					
					N/A		N/A			
					Yes	Surface Condition? (G/P)	Good			

