

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 46804 Main Street: ARBOR CREST CT **Cross Street: FOUNTAINGROVE DR** Location: ADA ID: E43037CACBB9 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 22.5

Codes/Mitigation Info/Possible Solution



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 **FOUNTAINGROVE DR** None ARBOR CREST CT None

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.2.2

Total Cost: 3200.00

Field Measurements/Component Compliance							
c	Compliance Description			Compliance Desc		Description	Data
N	/A Ram	p Length (in)	47.0	No	Ramp	Slope (%)	10.4
N	o Ram	p Width (in)	43.0	Yes	Ramp	XSlope (%)	4.6
N	/A Flare	e Type LT	N/A	N/A	Flare	Type RT	N/A
N	/A Flare	e Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N	/A Flare	Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N	/A Land	ing Length (in)	N/A	N/A	DWS	Provided?	N/A
N	/A Land	ing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N	/A Land	ing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N	/A Land	ing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N	/A Land	ing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N	/A Shar	ed Landing?	N/A				
N	/A Gutte	er Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
N/	/A Gutte	er Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
N	/ A Paint	ted X Walk1?	No	N/A	Painte	ed X Walk2?	No
	X Wa	alk 1 Direction	To NW		X Wa	lk 2 Direction	To SW
N	/A X Wa	alk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Wa	alk 1 Slope (%)	8.5		X Wa	lk 2 Slope (%)	4.4
	X Wa	alk 1 X Slope (%)	1.7		X Wa	lk 2 X Slope (%)	5.3
N	/A Ram	p inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
	Road	d Slope (%)	5.9	N/A	Clear	Space?	N/A
	Road	d X Slope (%)	5.9	N/A	Clear	Space to XWalk (in)	N/A
N	/A Any	Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A
	Obst	ruction Type			Storm	Grate/Utility Type	
			N/A				N/A
				Yes	Surfa	ce Condition? (G/P)	Good
	and the same of th		,	-		. ,	





