

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 54049 Main Street: DISTRICT SOUTH DR Cross Street: DISTRICT\_SOUTH\_DR Location: NE ADA ID: E43C17C5880C Ramp Type: Directional1 Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



**DISTRICT SOUTH DR** Street 1 Name Stop Condition-Street 1 StopSign Street 2 Name N/A Stop Condition-Street 2 N/A

o/Possible Solution			Field Measurements/Component Compliance					
Possible Solutions:			Comp	liance Description	Data	Comp	liance Description	Data
Remove & Replace Entire	e Ran	np.	N/A	Ramp Length (in)	82.5	N/A	Grade Break?	N/A
•		•	Yes	Ramp Width (in)	59.0	N/A	Grade Break Slope (%)	0.0
			No	Ramp Slope (%)	9.3	N/A	Grade Break XSlope (%)	0.0
			No	Ramp XSlope (%)	2.5			
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A			N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
<b>\</b>			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
R304.2.2, R304.5.3			N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
N. Control of the Con			N/A	Painted X Walk1?	Yes		Road Slope (%)	1.7
				X Walk 1 Direction	To W		Road X Slope (%)	3.3
				X Walk 1 Width (in)	90.0		Clear Space?	N/A
				X Walk 1 Slope (%)	1.7	N/A	Clear Space to XWalk (in)	N/A
				X Walk 1 X Slope (%)	3.3	N/A	Storm Grate/Utility Hazard?	N/A
			N/A	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type	
			N/A	Any Obstructions?	N/A			N/A
Total Cost:	\$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
					N/A	N/A	Curb Slope (%)	3.1





