## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16684 Main Street: SELWYN_FARMS_LN Cros				SELWYN_OAKS_CT	Location:	NW		
· · · · -								33.75
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
SELUVILIONES OF S	Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
	Remove & Replace Curb Ramp W	Vith	N/A	Ramp Length (in)	36.0	Yes	Ramp Slope (%)	6.8
	Two New Directional Ramps or Equivalent.		No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	7.6
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	8		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	4			X Walk 1 Direction	To S		X Walk 2 Direction	To E
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name SELWYN OAKS CT				X Walk 1 Slope (%)	1.5		X Walk 2 Slope (%)	4.7
Stop Condition-Street 2 StopSign				X Walk 1 X Slope (%)	3.1		X Walk 2 X Slope (%)	3.4
Street 2 Name SELWYN FARMS LN			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 None				Road Slope (%)	5.1	N/A	Clear Space?	N/A
				Road X Slope (%)	0.1	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

**Yes** Surface Condition? (G/P)

Good

