

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 7240	Main Str	Main Street: MONTEITH_DR			TOM_HUNTER_RD	Location:	SE		
ADA ID: E486266B1E0D	Ramp Ty	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: N			o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
A CONTRACTOR OF THE OWNER		Possible Solutions:		Compliance Description D			ta Compliance Description Data		
and the second and	S Malan a 1	Remove & Replace Entire Ramp	-	N/A	Ramp Length (in)	59.5	No	Ramp Slope (%)	10.3
and the second second				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	3.2
	AR The			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
The second	ALL OF THE			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	Mar and a start water			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
TON HUNTER RD				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Volta	- ANTRA C	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
6.000		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
6.				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	1 6			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	1 14.			N/A	Shared Landing?	N/A			
	à - 11	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	P.	Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
THE PART	11			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	1 10				X Walk 1 Direction	To W		X Walk 2 Direction	N/A
	6			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	MONTEITH DR	-			X Walk 1 Slope (%)	3.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	StopSign				X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	N/A
Street 2 Name	. c N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
					••	N/A			N/A

es Surface Condition? (G/P)

Good

