

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 16930	Main Street: BUCKNELL_AV			Cross Street: ROSWELL_AV				Location:	W	
ADA ID: E4AEF7E3E855 Ramp Type: Directional1		Initial I	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	1.25		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
8 1 1 1	NR-AN	Possible Solutions:		Compliance Description			Data Compliance Description			
		Remove & Replace Entire Ram	p.	N/A	Ramp Length (in)	102.0	N/A	Grade Break?	N/A	
	CONTE ON			Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0	
19. Was	2 10 /			Yes	Ramp Slope (%)	7.6	N/A	Grade Break XSlope (%)	0.0	
A REAL PROPERTY AND A REAL	18			No	Ramp XSlope (%)	3.4				
HT I	1.18			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
6 A				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
the second s	W. L. Low	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
A A A A A A A A A A A A A A A A A A A	Start A T			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
The states			N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A		
	AN ANALY			N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
The second s	1000	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
Ret		R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
				N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
				N/A	Painted X Walk1?	No		Road Slope (%)	3.0	
Street 1 Name BU	CKNELL AV				X Walk 1 Direction	To NE		Road X Slope (%)	1.5	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	3.0	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.5	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	6.9	

