

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 52081	081 Main Street: LAWYERS_RD			Cross Street: E_W_T_HARRIS_BV				Location:	SE
ADA ID: E4C806A56F40 Ramp Type: Perp			Initial I	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		Data
		Remove & Replace Entire Ram	0.	N/A	Ramp Length (in)	94.5	No	Ramp Slope (%)	8.9
				Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.1
	S CALLER LINE			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
5 b				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
5 m H				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
E LAWAR	1 Mar			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	the second second	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
E t		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	BE S.			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Enter State				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
6.ILT SILO	No.			N/A	Shared Landing?	N/A			
	12 16 10 10	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
JR. DI		Not Found, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
A P R SHOLE					X Walk 1 Direction	To N		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	122.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	LAWYERS RD				X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	1.8		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

**Yes** Surface Condition? (G/P)

Good

