

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 44824 Ma	Main Street: CLANTON_RD				Cross Street: GOLDEN_RIDGE_LN				Location:	NW	
ADA ID: E4D8BFB6BD09 Ra	Ramp Type: Directional1			Initial	Initial Pass/Fail: Fail Overall Complia			ance: No Severity Score:		22.5	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:			Compliance Description		Data	Data Compliance Description			
	and the	Remove & Replace Ent	ire Ran	ıp.	N/A	Ramp Length (in)	85.0	N/A	Grade Break?	N/A	
	al inte			•	No	Ramp Width (in)	47.0	N/A	Grade Break Slope (%)	0.0	
FEILE WE AND	31				No	Ramp Slope (%)	11.1	N/A	Grade Break XSlope (%)	0.0	
	1 Ales				No	Ramp XSlope (%)	3.8				
	N. B				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	Service				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
	Man .	Surveyor Notes:			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	Tan Tr	N/A			N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
	CARTIN				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
B. GOLDEN RIDGE UN - 5	1				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
t.	The second				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
	12 43	PROW/ADA:			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
		R304.5.1, R304.2.2, R3	04.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
		,,,,			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
					N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
					N/A	Painted X Walk1?	Yes		Road Slope (%)	0.2	
Street 1 Name CLANTO	NRD					X Walk 1 Direction	To NE		Road X Slope (%)	0.0	
Stop Condition-Street 1	None					X Walk 1 Width (in)	117.0		Clear Space?	N/A	
Street 2 Name	N/A					X Walk 1 Slope (%)	0.2	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A					X Walk 1 X Slope (%)	0.0	N/A	Storm Grate/Utility Hazard?	N/A	
					N/A	Ramp inside XWalk1?	Yes		Storm Grate/Utility Type		
					N/A	Any Obstructions?	N/A			N/A	
		Total Cost:	\$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
							N/A	N/A	Curb Slope (%)	5.7	

