

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

62.5

61.0

5.1

2.3

6.9

6.3

N/A

No

N/A

3.4

3.4

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Good 13.9

To SE

Intersection ID: 13177 Main Street: BETHEL RD **Cross Street: CARTIER WY** Location: Ν **Overall Compliance: No** 0 **ADA ID: E585C269CBE8** Ramp Type: Combination1Diag Initial Pass/Fail: Fail **Severity Score:**

Compliance Description

Road Slope (%)

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance Data

Compliance Description



Street 1 Name Stop Condition-Street 1 **BETHAL RD** Street 2 Name Stop Condition-Street 2 **CARTIER WY** Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

None

None

Not Found, R304.5.1, R304.5.3, R304.3.2

Total Cost:

N/A Ramp Length RT (in) N/A Ramp Length LT (in) 63.5 58.5 Yes Ramp Width LT (in) Yes Ramp Width RT (in) No Ramp Slope LT (%) 11.8 Yes Ramp Slope RT (%) Ramp XSlope LT (%) No Ramp XSlope RT (%) Yes 1.4 N/A Ramp Length (in) 59.0 Yes Ramp Slope (%) 40.5 No Ramp XSlope (%) No Ramp Width (in) N/A Flare Type LT N/A N/A Flare Type RT N/A N/A N/A Flare Slope LT (%) Flare Slope RT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A **DWS Contrast?** N/A Landing Width (in) N/A Landing Slope (%) N/A N/A DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A N/A Painted X Walk1? No Painted X Walk2? To SW X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in) 0.8 X Walk 2 Slope (%) X Walk 1 Slope (%) X Walk 1 X Slope (%) 7.7 X Walk 2 X Slope (%) N/A Ramp inside XWalk1? N/A N/A Ramp inside XWalk2?

3.4

5.3

N/A

N/A

N/A

Yes

Clear Space?

Any Obstruction?

Obstruction Type

Curb Slope (%)

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)







3200.00