


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 8445	Main Street: IRMA_ST	Cross Street: LASALLE_ST	Location: NE
ADA ID: E594F3B71E60	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 46.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance													
<div></div> <div>Street 1 NameIRMA ST</div> <div>Stop Condition-Street 2StopSign</div> <div>Street 2 NameLASALLE ST</div> <div>Stop Condition-Street 1None</div>			Possible Solutions:			Compliance			Description			Data				
			Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.			N/A			Ramp Length (in)			60.0				
			Surveyor Notes:			N/A			No			Ramp Width (in)			36.5	
									N/A			Flare Type LT			N/A	
			PROW/ADA:			Not Found, R304.5.1, R304.2.2, R304.5.3			N/A			Flare Slope LT (%)			N/A	
									N/A			Flare Traversable LT?			N/A	
									N/A			Landing Length (in)			N/A	
									N/A			Landing Width (in)			N/A	
									N/A			Landing Slope (%)			N/A	
									N/A			Landing X Slope (%)			N/A	
									N/A			Landing Curb? (Y/N)			N/A	
									N/A			Shared Landing?			N/A	
									N/A			Gutter Ponding?			N/A	
									N/A			Gutter Lip Ht (in)			N/A	
			N/A			Painted X Walk1?			No							
						X Walk 1 Direction			To W							
			N/A			X Walk 1 Width (in)			N/A							
						X Walk 1 Slope (%)			0.0							
						X Walk 1 X Slope (%)			9.9							
			N/A			Ramp inside XWalk1?			N/A							
			Road Slope (%)			10.5										
			Road X Slope (%)			8.3										
N/A			Any Obstructions?			N/A										
			Obstruction Type													
						N/A										
						Yes										

Total Cost:			\$	3200.00

