


Intersection ID: 51046	Main Street: LONGNOR_ST	Cross Street: PALATINE_LN	Location:	W
ADA ID: E5BADDF99D62	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No	Severity Score: 7.5

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	95.0	Yes	Ramp Slope (%)	6.2
	Remove & Replace Gutter.		Yes	Ramp Width (in)	60.0	Yes	Ramp XSlope (%)	1.1
			N/A	Flare Type LT	Sloped	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	4.8	No	Flare Slope RT (%)	11.6
			N/A	Flare Traversable LT?	Yes	N/A	Flare Traversable RT?	Yes
			Yes	Landing Length (in)	60.0	Yes	DWS Provided?	Yes
			Yes	Landing Width (in)	60.0	Yes	DWS Contrast?	Yes
			Yes	Landing Slope (%)	0.9	Yes	DWS Length (in)	24.0
			Yes	Landing X Slope (%)	0.1	Yes	DWS Full Width?	Yes
Surveyor Notes: N/A			N/A	Landing Curb? (Y/N)	No	No	DWS Offset (in)	3.0
			N/A	Shared Landing?	No			
			Yes	Gutter Ponding?	No	No	Gutter Slope (%)	7.1
			Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	2.3
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To E		X Walk 2 Direction	N/A
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	4.5		X Walk 2 Slope (%)	N/A
				X Walk 1 X Slope (%)	3.0		X Walk 2 X Slope (%)	N/A
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
PROW/ADA: Not Found, R304.2.3, R305.2, R304.5.4				Road Slope (%)	N/A	N/A	Clear Space?	Yes
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No
				Obstruction Type			Storm Grate/Utility Type	
						N/A		N/A
						Yes	Surface Condition? (G/P)	Good
	Total Cost:	\$ 2600.00						
Street 1 Name		LONGNOR ST						
Stop Condition-Street 2		None						
Street 2 Name		N/A						
Stop Condition-Street 1		N/A						

