

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

0.08

48.0

0.1

8.5

11.6

7.1

N/A

Intersection ID: 8126 Main Street: IRMA_ST Cross Street: NEWLAND_RD Location: SW

ADA ID: E5D1221730B6 Ramp Type: Combination1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 46.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
StopSign
Stop Condition-Street 1
IRMA ST
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

RT RP < 5%

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3, R304.3.2

Total Cost: \$ 1800.00

Compliance Description Data Compliance Description Ramp Length LT (in) N/A N/A 66.0 Ramp Length RT (in) 48.0 Yes Ramp Width LT (in) Yes Ramp Width RT (in) No Ramp Slope LT (%) 10.5 Yes Ramp Slope RT (%) Ramp XSlope LT (%) No Ramp XSlope RT (%) No 6.3 N/A Ramp Length (in) 48.0 Nο Ramp Slope (%) 41.0 No Ramp XSlope (%) No Ramp Width (in) N/A Flare Type LT N/A N/A Flare Type RT N/A N/A Flare Slope LT (%) N/A Flare Slope RT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A Landing Length (in) N/A N/A DWS Provided? N/A N/A N/A Landing Width (in) **DWS Contrast?** N/A Landing Slope (%) N/A N/A DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A Shared Landing? N/A N/A **Gutter Ponding?** N/A N/A Gutter Slope (%) N/A N/A Gutter Lip Ht (in) N/A Gutter X Slope (%) N/A Painted X Walk2? N/A Painted X Walk1? No To W X Walk 1 Direction X Walk 2 Direction X Walk 1 Width (in) N/A X Walk 2 Width (in) 4.2 X Walk 1 Slope (%) X Walk 2 Slope (%) X Walk 1 X Slope (%) 4.0 X Walk 2 X Slope (%)

N/A

N/A

N/A

N/A

N/A







N/A

Ramp inside XWalk1?

Road Slope (%)

N/A Any Obstruction? N/A
Obstruction Type

N/A

N/A

Storm Grate/Utility Hazard?
Storm Grate/Utility Type

N/A

Yes Surface Condition? (G/P)
Curb Slope (%)

N/A

Ramp inside XWalk2?

Clear Space to XWalk (in)

Clear Space?