## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15243	on ID: 15243 Main Street: ALBEMARLE_RD			street:	REGAL_OAKS_DR	Location:	NW		
ADA ID: E5D6AF3E0ADI	DA ID: E5D6AF3E0ADF Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	22.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description			Data Compliance Description		
		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	Vith	N/A	Ramp Length (in)	60.0	No	Ramp Slope (%)	9.1
WALK AND				No	Ramp Width (in)	46.0	No	Ramp XSlope (%)	5.0
and the second				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
and the way is the state of the				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	the trans			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
The strength of the second				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
The second second second				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
J. Starting and the start of th		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
(D) - '				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
ALBEMAR				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
ATT	8 8			N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
203	L. L	Not Found, R304.5.1, R304.2.2,		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
THE R. W.	<u>6</u>	R304.5.3		N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	Yes
the state of the second	47				X Walk 1 Direction	To S		X Walk 2 Direction	To E
				N/A	X Walk 1 Width (in)	110.0	N/A	X Walk 2 Width (in)	108.0
Street 1 Name	ALBEMARLE RD	_			X Walk 1 Slope (%)	1.7		X Walk 2 Slope (%)	0.7
Stop Condition-Street 2	Signal				X Walk 1 X Slope (%)	2.9		X Walk 2 X Slope (%)	0.9
Street 2 Name	REGAL OAKS DR			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	Yes
Stop Condition-Street 1	Signal				Road Slope (%)	1.4	N/A	Clear Space?	N/A
					Road X Slope (%)	0.0	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 32	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A
1							1		

Yes Surface Condition? (G/P)

Good

