## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: PINEVILLE-MATTHEWS_RD Cross Street: N/A								Location:	NE
ADA ID: E5E20868B	BCAA Ramp Type: PerpDiag Ini				al Pass/Fail: Fail Overall Compliance: No				46.25
Codes/Mitigation Info/Possible Solution				tial Pass/Fail: Fail Overall Compliance: No Severity Score: 46.2 Field Measurements/Component Compliance					
	HULL REPORT	Possible Solutions:		Compliance Description		Data	Data Compliance Description		Data
10-1		Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.	ith	N/A	Ramp Length (in)	59.0	No	Ramp Slope (%)	8.8
				No	Ramp Width (in)	40.0	No	Ramp XSlope (%)	7.1
			I	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			I	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A REPORT OF			1	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Carl in 19744	Surveyor Notes:	1	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
di d		N/A	1	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			I	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
PINEVILLE	MATTHEWS_RD			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Me	~ ~ ~ …		I	N/A	Shared Landing?	N/A			
A State of the second second	C. C	PROW/ADA:	1	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
<u>6.</u>	Maning with the state	Not Found, R304.5.1, R304.2.2, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
and the second	Shin wants m			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
The second	THE REPORT				X Walk 1 Direction	To W		X Walk 2 Direction	To S
Con Stand	the second second		1	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	ENTRANCE	_			X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	5.7
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	5.8		X Walk 2 X Slope (%)	2.2
Street 2 Name	PINEVILLE-MATTHEWS RD		1	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None				Road Slope (%)	5.5	N/A	Clear Space?	N/A
					Road X Slope (%)	3.4	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 320	00.00		Obstruction Type			Storm Grate/Utility Type	
					2.	N/A			N/A
1									



