cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		•			-					
Intersection ID: 20172	Main Street: CORTELYOU_RD			Cross	Street:	FOXCROFT_RD	Location:	NE		
ADA ID: E65A99653B5A	Ramp Type: PerpDiag			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	33.75
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:			Compliance Description			Data Compliance Description		
330		Remove & Replace Curb Ramp Two New Directional Ramps or Equivalent.	Ramp	With	N/A	Ramp Length (in)	93.0	No	Ramp Slope (%)	12.8
			•		No	Ramp Width (in)	45.0	Yes	Ramp XSlope (%)	1.9
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
ALCONTRACTOR DE		Surveyor Notes:			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
					N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	Riter				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
the second second	NILLYOU RD				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
The second states				N/A	Shared Landing?	N/A				
Kara	E All All	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	A Claim	Not Found, R304.5.1, R30	14 2 2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	A CAR	Not i build, K304.3.1, K304.2.2			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
Max 1 1258					X Walk 1 Direction	To NW		X Walk 2 Direction	To SW	
En i La la				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	FOXCROFT RD	•				X Walk 1 Slope (%)	2.3		X Walk 2 Slope (%)	0.2
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	2.4		X Walk 2 X Slope (%)	0.3
Street 2 Name	CORTELYOU RD				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	StopSign					Road Slope (%)	0.5	N/A	Clear Space?	N/A
	otopolgii					Road X Slope (%)	6.5	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	0.5 N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	¢	3200.00	11/5	Obstruction Type	17/4		Storm Grate/Utility Type	11/2
		10121 0051.	Ψ	5200.00		Costruction Type	N/A		Giorni Grate/Otimity Type	N/A
							IN/A			IN/A

Yes Surface Condition? (G/P)

Good

