

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 54374 Main Street: GRIER RD Cross Street: OLD CONCORD RD Location: Ε **Severity Score:** ADA ID: E666111E9A51 Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No** 10

Codes/Mitigation Info/Possible Solution



OLD CONCORD RD Street 1 Name Stop Condition-Street 2 Signal Street 2 Name N/A Stop Condition-Street 1 N/A

Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: R304.5.1, R304.5.3

Total Cost: 1850.00

| Field Measurements/Component Compliance | | | | | |
|---|-----------------------|-------|--------------------|-----------------------------|------|
| Compliance Description Data | | Comp | liance Description | Data | |
| N/A | Ramp Length (in) | 83.0 | Yes | Ramp Slope (%) | 7.2 |
| No | Ramp Width (in) | 47.0 | No | Ramp XSlope (%) | 3.7 |
| N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| N/A | Shared Landing? | N/A | | | |
| N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| N/A | Painted X Walk1? | Yes | N/A | Painted X Walk2? | N/A |
| | X Walk 1 Direction | To NW | | X Walk 2 Direction | N/A |
| N/A | X Walk 1 Width (in) | 105.0 | N/A | X Walk 2 Width (in) | N/A |
| | X Walk 1 Slope (%) | 4.2 | | X Walk 2 Slope (%) | N/A |
| | X Walk 1 X Slope (%) | 1.4 | | X Walk 2 X Slope (%) | N/A |
| N/A | Ramp inside XWalk1? | Yes | N/A | Ramp inside XWalk2? | N/A |
| | Road Slope (%) | N/A | N/A | Clear Space? | N/A |
| | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A |
| N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | Obstruction Type | | | Storm Grate/Utility Type | |
| | | N/A | | | N/A |
| | | | Yes | Surface Condition? (G/P) | Good |
| | | | | | |





