

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

N/A

N/A

6.5

Good

Intersection ID: 52127 Main Street: VALLEYDALE\_RD Cross Street: FRED\_D\_ALEXANDER\_BV Location: N

ADA ID: E6C3C7D12721 Ramp Type: Combination1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 26.25

Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Signal
Stop Condition-Street 1
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.

Surveyor Notes:

RP < 5%

PROW/ADA:

Not Found, R304.3.2, R304.5.3

Total Cost: \$ 1800.00



N/A

Yes

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Curb Slope (%)





