


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: N/A	Main Street: MONROE_RD	Cross Street: N/A	Location: NW
ADA ID: E6D80DB9FAEE	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No
		Severity Score: 12.5	

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance						
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data	
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)	60.0	Yes	Ramp Slope (%)	5.1	
			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	5.2	
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
Surveyor Notes:	N/A		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
			N/A	Shared Landing?	N/A				
	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
	Not Found, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A	
				X Walk 1 Direction	To S		X Walk 2 Direction	N/A	
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
				X Walk 1 Slope (%)	0.9		X Walk 2 Slope (%)	N/A	
				X Walk 1 X Slope (%)	0.6		X Walk 2 X Slope (%)	N/A	
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Street 1 Name	ENTRANCE			Road Slope (%)	N/A	N/A	Clear Space?	N/A	
	Stop Condition-Street 2		None		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
	Street 2 Name		N/A	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Stop Condition-Street 1		N/A		Obstruction Type		Storm Grate/Utility Type		
						N/A		N/A	
						Yes	Surface Condition? (G/P)	Good	
	Total Cost:		\$ 1850.00						

