

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: 10024487 Main Street: CROWN CENTRE DR **Cross Street: N/A** Location: ADA ID: E70E3FEB87F0 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 21.25

**Codes/Mitigation Info/Possible Solution** 

None

**ENTRANCE** 

StopSign

## Field Measurements/Component Compliance



**CROWN CENTRE DR** Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1

Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

R304.5.1, R304.2.2

No	
N/A	
IV/A	
N/A	
N/A	
N/A	
	N/A N/A N/A N/A N/A N/A N/A N/A N/A

Total Cost: 3200.00

Compliance Description Data		Comp	liance Description	Data	
N/A	Ramp Length (in)	110.0	No	Ramp Slope (%)	8.4
No	Ramp Width (in)	46.0	Yes	Ramp XSlope (%)	0.5
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	0.5	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	4.9		X Walk 2 Slope (%)	0.3
	X Walk 1 X Slope (%)	1.1		X Walk 2 X Slope (%)	4.3
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	0.5	N/A	Clear Space?	N/A
	Road X Slope (%)	1.9	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type		l	Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good





