

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 6583 Main Street: FAIRES_FARM_RD Cross Street: MCLEAN_RD Location: NW

ADA ID: E72BD0D83C47 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

MCLEAN RD None FAIRES FARM RD StopSign Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

N/A

Surveyor Notes:

PROW/ADA:

R304.5.1, R304.2.2

1	



Total Cost:



3200.00

Field Measurements/Component Compliance								
Comp	liance Description	Data	Comp	liance	Description	Data		
N/A	Ramp Length (in)	45.0	No	Ram	Slope (%)	10.2		
No	Ramp Width (in)	47.0	Yes	Ramp	XSlope (%)	2.0		
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	No		
	X Walk 1 Direction	To S		X Wa	lk 2 Direction	To E		
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	3.6		X Wa	lk 2 Slope (%)	4.3		
	X Walk 1 X Slope (%)	3.5		X Wa	lk 2 X Slope (%)	2.8		
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	inside XWalk2?	N/A		
	Road Slope (%)	0.8	N/A	Clear	Space?	N/A		
	Road X Slope (%)	3.8	N/A	Clear	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A		
	Obstruction Type			Storn	n Grate/Utility Type			
		N/A				N/A		
			Yes	Surfa	ce Condition? (G/P)	Good		