

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Severity Score:

Storm Grate/Utility Type

Surface Condition? (G/P)

N/A

Good

Intersection ID: 18554 Main Street: HEATHMOOR LN **Cross Street: SHARON LN** Location: ADA ID: E782220AF5D5 Initial Pass/Fail: Fail **Overall Compliance: No** 17.5

Codes/Mitigation Info/Possible Solution

Ramp Type: PerpDiag

Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 **HEATHMOOR LN** StopSign **SHARON LN** None Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1

Total Cost: 3200.00

Field Measurements/Component Compilance						
Compliance Description		Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	58.5	Yes	Ram	Slope (%)	6.5
No	Ramp Width (in)	34.0	Yes	Ramp	XSlope (%)	0.0
N/A	Flare Type LT	N/A	N/A Flare Type RT		N/A	
N/A	Flare Slope LT (%)	N/A	N/A Flare Slope RT (%)		N/A	
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	No
	X Walk 1 Direction	To NE		X Wa	lk 2 Direction	To NW
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	0.2		X Wa	lk 2 Slope (%)	2.1
	X Walk 1 X Slope (%)	2.5		X Wa	lk 2 X Slope (%)	0.9
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	inside XWalk2?	N/A
	Road Slope (%)	1.6	N/A	Clear	Space?	N/A
	Road X Slope (%)	2.0	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A

N/A







Obstruction Type