

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

N/A

N/A

N/A

N/A

8.9

8.0

N/A

No

N/A

3.1

1.4

N/A

N/A

To NE

Intersection ID: 14797 Main Street: LYNDHURST AV **Cross Street: MAGNOLIA AV** W Location: **Overall Compliance: No Severity Score:** 0 ADA ID: E7B9AE686022 Ramp Type: Combination2Diag Initial Pass/Fail: Fail

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

N/A

N/A

N/A

Nο

Yes

N/A

Compliance Description

Ramp Length RT (in)

Ramp Width RT (in)

Ramp Slope RT (%)

Ramp XSlope RT (%)

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space?

Flare Traversable RT?

Data

N/A

N/A

N/A

N/A

72.5

49.0

N/A

No

N/A

1.2

3.7

N/A

3.3

To SE



Street 1 Name Stop Condition-Street 1 Street 2 Name Stop Condition-Street 2

StopSign LYNDHURST AV StopSign **MAGNOLIA AV**

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.2.2

Total Cost:

Compliance Description Ramp Length LT (in) N/A N/A Ramp Width LT (in) N/A Ramp Slope LT (%) N/A Ramp XSlope LT (%) N/A Ramp Length (in) Yes Ramp Width (in) N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) N/A Landing Width (in) N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A Gutter Ponding? N/A Gutter Lip Ht (in) N/A Painted X Walk1?



N/A

3200.00

Road X Slope (%) 3.1 N/A Clear Space to XWalk (in) N/A N/A Any Obstruction? N/A **Obstruction Type** N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good 17.3 Curb Slope (%)

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)



