

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

64.0

27.0

14.9

2.5

10.2

7.6

N/A

Good 13.1

Intersection ID: 10031454 Main Street: MCDONALD_AV Cross Street: N/A Location: S

ADA ID: E7DB2BA5BF08 Ramp Type: Combination2 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 50

Compliance Description

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Compliance Description

Data

N/A

N/A

N/A

N/A

Yes

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Any Obstruction?

Obstruction Type

Curb Slope (%)



Street 1 Name
StopSign
Stop Condition-Street 1
ENTRANCE
Street 2 Name
N/A
Stop Condition-Street 2
N/A

Possible Solutions:

Remove & Replace Entire Ramp.


Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2, R304.5.3, R304.3.2

Total Cost:









1600.00