

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Good

Surface Condition? (G/P)

Intersection ID: 17072 Main Street: IDLEWILD\_RD Cross Street: DION\_AV Location: S

ADA ID: E7DE7DA90DF5 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 25

## Codes/Mitigation Info/Possible Solution

## Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

DION AV StopSign IDLEWILD RD None Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes: **N/A** 

PROW/ADA:

Not Found, R304.2.2

Total Cost:

Compliance Description			Data	Compliance Description		Data
ĺ	N/A	Ramp Length (in)	68.0	No	Ramp Slope (%)	13.6
•	Yes	Ramp Width (in)	48.0	Yes	Ramp XSlope (%)	2.0
ı	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
ı	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
ı	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
-	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
-	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
ı	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
ı	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
-	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
-	N/A	Shared Landing?	N/A			
-	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
ı	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
-	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
-	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	0.4		X Walk 2 Slope (%)	1.3
		X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	0.5
I	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	0.4	N/A	Clear Space?	N/A
		Road X Slope (%)	1.0	N/A	Clear Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type			Storm Grate/Utility Type	







3200.00