cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9757	Main Street: HIGHLAKE_DR			Cross Street: THE_PLAZA					Location:	SW
ADA ID: E80A8B7EFF2A	A Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No					o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance							
	And the second	Possible Solutions:		Compliance Description			Data	Data Compliance Description		
	The second	Remove & Replace E	ntire Ramp		N/A	Ramp Length (in)	60.5	No	Ramp Slope (%)	8.8
			-		No	Ramp Width (in)	40.0	Yes	Ramp XSlope (%)	1.1
	-001				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
& b	A IN				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
THE PLAN					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Contraction of the second seco					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
Min-Ma	the second secon				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
The state of the second state of the					N/A	Shared Landing?	N/A			
	- The second second	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
The Property of the State	Not Found, R304.5.1	. R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
A THE PARTY	25	,			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To NE		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	THE PLAZA					X Walk 1 Slope (%)	1.4		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	1.9		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good

