

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14212 Main Street: HAWKINS ST Cross Street: W_TREMONT_AV Location: NE ADA ID: E81A883A07FC Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 26.25

Codes/Mitigation Info/Possible Solution



HAWKINS ST Street 1 Name Stop Condition-Street 2 StopSign Street 2 Name W TREMONT ST Stop Condition-Street 1 StopSign Possible Solutions: Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent. Surveyor Notes: N/A PROW/ADA: R304.2.2, R304.5.3

Total Cost: 3200.00

Field Measurements/Component Compliance							
Compliance Description		Data	Compli	ance	Description	Data	
N	I/ A Ram	np Length (in)	74.0	No	Ramp	Slope (%)	13.0
Υ	es Ram	np Width (in)	72.0	No	Ramp	XSlope (%)	2.1
N	/ A Flar	e Type LT	N/A	N/A	Flare	Type RT	N/A
N	I/ A Flar	e Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N	I/A Flar	e Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N	I/A Land	ding Length (in)	N/A	N/A	DWS	Provided?	N/A
N	I/A Land	ding Width (in)	N/A	N/A	DWS	Contrast?	N/A
N	I/A Land	ding Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N	I/A Land	ding X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N	I/A Land	ding Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N	I/A Sha	red Landing?	N/A				
N	I/A Gutt	ter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
N	/A Gutt	ter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
N	I/A Pain	ited X Walk1?	No	N/A	Painte	ed X Walk2?	Yes
	ΧW	alk 1 Direction	To W		X Wa	lk 2 Direction	To SW
N	I/A XW	alk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	114.0
	ΧW	alk 1 Slope (%)	2.8		X Wa	lk 2 Slope (%)	5.3
	ΧW	alk 1 X Slope (%)	5.6		X Wa	lk 2 X Slope (%)	5.0
N	I/A Ram	np inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	Yes
	Roa	d Slope (%)	6.7	N/A	Clear	Space?	N/A
	Roa	d X Slope (%)	1.9	N/A	Clear	Space to XWalk (in)	N/A
N	I/A Any	Obstructions?	N/A	N/A	Storm	n Grate/Utility Hazard?	N/A
	Obs	truction Type			Storm	n Grate/Utility Type	
			N/A				N/A
				Yes	Surfa	ce Condition? (G/P)	Good





