

Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 53505	Main Street: ALLISON_WOODS_DR	Cross Street: ALLISON_LN	Location: SW
ADA ID: E84E357FF69A	Ramp Type: BlendTrans2	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 15.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
	Possible Solutions:		Compliance	Description	Data	Compliance	Description	Data
	Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Remove & Replace Gutter.		N/A	Ramp Length (in)	106.0	Yes	BlendTrans Slope (%)	1.8
			Yes	Ramp Width (in)	48.0	No	BlendTrans XSlope (%)	2.6
			N/A	Flare Type LT	None	N/A	Flare Type RT	None
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	No	DWS Provided?	No
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	No
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	No
Surveyor Notes: NO CURB LINE PROW/ADA: R304.5.3, R305, R304.5.4			N/A	Landing Curb? (Y/N)	No	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	No			
			Yes	Gutter Ponding?	No	No	Gutter Slope (%)	8.3
			Yes	Gutter Lip Ht (in)	0.0	Yes	Gutter X Slope (%)	1.8
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To E		X Walk 2 Direction	To N
				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	5.1		X Walk 2 Slope (%)	4.0
				X Walk 1 X Slope (%)	4.9		X Walk 2 X Slope (%)	5.6
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
			Road Slope (%)	2.0		Clear Space?	Yes	
			Road X Slope (%)	7.2	N/A	Clear Space to XWalk (in)	N/A	
		Yes	Any Obstructions?	No	Yes	Storm Grate/Utility Hazard?	No	
			Obstruction Type			Storm Grate/Utility Type		
					N/A			N/A
						Yes	Surface Condition? (G/P)	Good
						N/A	Curb Slope (%)	N/A

