


Intersection ID: 7441		Main Street: W_SUGAR_CREEK_RD		Cross Street: WILSON_LN		Location:		NW			
ADA ID: E86F7B5BEC1E		Ramp Type: ParaDiag		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 12.5			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance							
<div></div> <div>Street 1 Name<div>WILSON LN</div></div> <div>Stop Condition-Street 1<div>StopSign</div></div> <div>Street 2 Name<div>W SUGAR CREEK RD</div></div> <div>Stop Condition-Street 2<div>None</div></div>				Possible Solutions:		Compliance		Description		Data	
				Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A		Ramp Length LT (in)		59.0	
				Surveyor Notes: <div>N/A</div>		Yes		Ramp Width LT (in)		54.5	
						No		Ramp Slope LT (%)		8.9	
						Yes		Ramp XSlope LT (%)		0.5	
						N/A		Landing Length (in)		N/A	
				PROW/ADA: <div>R304.3.2</div>		N/A		Landing Width (in)		N/A	
						N/A		Landing Slope (%)		N/A	
						N/A		Landing X Slope (%)		N/A	
						N/A		Landing Curb? (Y/N)		N/A	
Total Cost: <div>\$ 3200.00</div>		N/A		Shared Landing?		N/A					
		N/A		Gutter Ponding?		N/A					
		N/A		Gutter Lip Ht (in)		N/A					
		N/A		Painted X Walk1?		No					
				X Walk 1 Direction		To S					
		N/A		X Walk 1 Width (in)		N/A					
				X Walk 1 Slope (%)		0.7					
				X Walk 1 X Slope (%)		0.2					
		N/A		Ramp inside XWalk1?		N/A					
				Road Slope (%)		1.7					
		Road X Slope (%)		2.2							
N/A		Any Obstructions?		N/A							
		Obstruction Type		N/A							
				N/A							
				Yes							
				N/A							
				Surface Condition? (G/P)							
				Good							
				Curb Slope (%)							
				4.5							

