

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



		•			. /						
Intersection ID: 10862 Main Street: N_GRAHAM_ST					Cross Street: DALTON_AV				Location:	SW	
ADA ID: E8A99F307271	Ramp Type: Combination1			Initia	Initial Pass/Fail: Fail Overall Compliance			ice: No Severity Score: 8.7		8.75	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance						
		Possible Solutions:			Compliance Description			Data Compliance Description Data			
		Remove & Replace Enti	np.	N/A	Ramp Length LT (in)	55.0	N/A	Ramp Length RT (in)	41.5		
				Yes	Ramp Width LT (in)	59.5	Yes	Ramp Width RT (in)	72.0		
					Yes	Ramp Slope LT (%)	3.8	Yes	Ramp Slope RT (%)	5.1	
	6 8 mpm				Yes	Ramp XSlope LT (%)	0.9	Yes	Ramp XSlope RT (%)	1.4	
DALTONLAY				N/A	Ramp Length (in)	28.0	Yes	Ramp Slope (%)	7.2		
	A				No	Ramp Width (in)	39.0	Yes	Ramp XSlope (%)	0.1	
· E		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	6.	LT RP < 5%			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	5.				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
	A Carlotte				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	K				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
	Martin	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	REAL	Not Found, R304.5.1			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	7			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
				N/A	Shared Landing?	N/A					
					N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	Signal				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	N GRAHAM ST				N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A	
Street 2 Name	N/A					X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
Stop Condition-Street 2	N/A					X Walk 1 Width (in)	122.0		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	0.0		X Walk 2 Slope (%)	N/A	
						X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	N/A	
		Total Cost:	\$	1800.00	N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	N/A		Clear Space?	N/A	
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
+		and the second	1					N/A	Any Obstruction?	N/A	
					All a				Obstruction Type		
				110						N/A	
				- The				N/A	Storm Grate/Utility Hazard?	N/A	
					K				Storm Grate/Utility Type	11/2	
	Section and the	and friend and the second second								N/A	
		the letter the second		A CONTRACTOR				1			

