## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 19633	Main Str	Main Street: BROWN-GRIER_RD			Cross Street: MEADOWMEAD_CT				NW
ADA ID: E9175951BDF1	Ramp Ty	Ramp Type: BlendTrans2			Initial Pass/Fail: Fail Overall Compliance: No				10
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	23/1-1	Possible Solutions:		Compliance Description Da				Data	
		Remove & Replace Curb Ram	nn With	N/A	Ramp Length (in)	95.0	1	BlendTrans Slope (%)	2.7
		Two New Directional Ramps		No	Ramp Width (in)	47.0		BlendTrans XSlope (%)	3.0
		Equivalent.		N/A	Flare Type LT	N/A		Flare Type RT	N/A
				N/A	Flare Slope LT (%)		N/A	Flare Slope RT (%)	N/A
		4		N/A	Flare Traversable LT?	N/A		Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A		DWS Provided?	N/A
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A N/A
		,		N/A	<b>o</b> ( )	N/A			N/A N/A
A CONTRACTOR OF CONTRACTOR		N/A			Landing Slope (%)			DWS Length (in)	
EROUWE				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	B. Martin	19 19		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
				N/A	Shared Landing?	N/A			
		PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	at any states the			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	Cherry and the second				X Walk 1 Direction	To S		X Walk 2 Direction	To NE
	1 G MARKER				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name	<b>BROWN-GRIER RD</b>				X Walk 1 Slope (%)	4.6		X Walk 2 Slope (%)	1.1
Stop Condition-Street 1	StopSign				X Walk 1 X Slope (%)	0.2		X Walk 2 X Slope (%)	5.0
Street 2 Name	MEADOWMEAD CT			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	None				Road Slope (%)	1.5		Clear Space?	N/A
					Road X Slope (%)	5.6	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?		N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type	
		····· • •				N/A			N/A
						17/4			17/2

YesSurface Condition? (G/P)NoCurb Slope (%)

Good

9.2





