

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 45981	Main Str	Main Street: LAUREL_VALLEY_RD			Street:	MASON MILL_PL	Location:	NW		
ADA ID: E93110AAF08B	Ramp Ty	Ramp Type: PerpDiag			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	46.25
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:						Data Compliance Description		Data
		Remove & Replace Curb F		n With	N/A	Ramp Length (in)	48.0	No	Ramp Slope (%)	10.8
		Two New Directional Ramps Equivalent.			No	Ramp Width (in)	38.0	No	Ramp XSlope (%)	7.1
					N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A		Flare Slope RT (%)	N/A
1 Carl Rull 1					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes: N/A		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
					N/A	Landing Slope (%)	N/A		DWS Length (in)	N/A
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
and the sourt fills					N/A	<b>e</b> 1 ( )	N/A	N/A		N/A N/A
TUP South		the second se				Landing Curb? (Y/N)		N/A	DWS Offset (in)	N/A
	2 11 / 11 m				N/A	Shared Landing?	N/A			
5	1231 1 16 28	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
R304.5.1, R304.2			4.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
<u>6.</u>					N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
					X Walk 1 Direction	To S		X Walk 2 Direction	To E	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	MASON MIILL PL					X Walk 1 Slope (%)	5.3		X Walk 2 Slope (%)	9.4
Stop Condition-Street 2	StopSign					X Walk 1 X Slope (%)	4.4		X Walk 2 X Slope (%)	1.6
Street 2 Name	LAUREL VALLEY RD				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	None					Road Slope (%)	5.0	N/A	Clear Space?	N/A
						Road X Slope (%)	6.8	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$	3200.00		Obstruction Type			Storm Grate/Utility Type	
			Ŧ				N/A			N/A
							11/1			1975